Off-Channel Survey Report for: BK4RB2 Report Date: 12/28/1998 Last Modified: 12/28/19 At: 14:29:56 By: Page: 1

SITE INFORMATION

Site Identifier:

BK4RB2

Landowner Type: Federal

Site Name:

03.0435X

Landowner Name: USFS

WRIA:

Address:

Region: Trib to:

NS Baker R Address2: City:

River Mile:

18.70

River System:

State:

Legal Description: NW1/4S35T38NR9E

Baker R

Zipcode: Phone:

County:

Whatcom

Habitat Type:

lower valley wall tributary

Directions:

From Sedro-Woolley take highway 20 to the Baker Lake road and turn left. Take this road which passes Grandy Lake and Lake Shannon to Baker Lake and continue to Shannon creek approximately 25 miles from highway 20. The site crosses under the road 0.1 miles above Shannon Creek.

Area Overview:

Site is a very small, year around stream with a moderate gradient that offers a very small amount of rearing habitat for coho. Access to the site is limited to the times when the reservoir is full and the stream is high

Field Survey Information

Date: 11/11/1998 Observer: Barkdull Survey Type: initial

HABITAT INFORMATION

Water Source:

() Spring

() Groundwater

(x) Surface runoff

Flow:

() Intermittent(x) Year-round

Estimated Flows (cfs):

Lower end:0.1

Upper end:0.1

Water Temperature(C):

Lower end:9

Upper end:9

Receiving Water Temperature (C):7

Other Observations:

Site Area Measurements:

()Indirect

(x) Direct

() Combination

Widths: Channel:0.6

Ponds:

Depths: Channel:0.1

Ponds:

Wetlands: Wetlands:

Total length (includes ponds and wetlands):85

Total existing habitat area (est. m2):51

Unaccessible habitat:

Spawning area: Impounded area: Mainstem:0

Mainstem: Other rearing area:

Mainstem:51

Mainstem:

Tribs: Tribs:


Tribs:


Tribs:

Total:51 Total:

Total:0 Total:

Off-Channel Survey Report for:	BK4RB2 R	Report Date: 12	/28/1998 Last Modifie	d: 12/28/19	At: 14:29:56	By:	Page: 2
Spawning habitat conditions	(x) None	() Poor ()	Fair () Good ()	Exellent			
Describe spawning habitat:Stream has patches of small gravel but is so small (0.1 cfs on November 11) it is doubtful adult coho would be attracted to the site.							
Rearing habitat conditions: () None () Poor (x) Fair () Good () Exellent							
Describe pond and other rearing habitat:Stream is a moderate gradient with a few pools but is mostly riffles. Site has a 00 very dense canopy of vine maple and salmonberry throughout with good in stream woody debris.							
Describe unaccessible habitat: Stream continues to increase in gradient above the cascade to the road and is mostly cascades.							
Wetland type: () Bog	() Marsh	h ()S	crub-shrub	() Forest	ed		
Describe:							
Flooding potential: (x) l	_ow	() Medium	() High				
Describe:Stream appears very stable and is not affected by outside flood sources.							
FISH INFORMATION							
Site entry condition: (x) I	Poor	() Fair	() Good				
Describe:Site is only accessible when the reservoir is full and flows are high due to the steepness of the lake shoreline.							
Coho access and use: Juvenile (x) Unknown () None () Poor () Fair () Good Adult (x) Unknown () None () Poor () Fair () Good							
Describe: No fish were observed on the day of the survey.							
Other species access and use: () Chum () Pink () Sockeye () Chinook (x) Trout							
Describe:Trout use possible but unconfirmed							
ENHANCEMENT OPPORTUNITIES: None							
Project type:							
Equipment access:							
ADDITIONAL COMMENTS							
ATTACHMENTS AVAILABL	Ē						
(x) Aerials (x) Sketch () Other References	(x) Maps	s () S _i	pawning Surveys	() Juven	ile Trapping		





Illings trbt Boker Jest floor Showner.
0.0 0.8 0.1 cfs, access only of
high lake levels. 21 0.8 4% most Sing 5-19 V5 0,6 71 6,5 5% 850.5 BK4ABZ RM 18.7 MWS 35, T 38N, R9E 51m Habitat